## Message Text

UNCLASSIFIED

PAGE 01 STATE 152254

64

ORIGIN SY-10

INFO OCT-01 AF-05 ADP-00 /016 R

DRAFTED BY A/SY/T: JFPERDEW

8/1/73 EXT 20548

APPROVED BY A/SY/T: DGFISCHER
-----123639

R 022002Z AUG 73

FM SECSTATE WASHDC

TO AMEMBASSY PORT LOUIS

INFO AMEMBASSY PRETORIA

UNCLAS STATE 152254

E.O. 11652: N/A TAGS: ASEC

SUBJECT: DISINTEGRATOR PARTS

PORT LOUIS FOR PSO FROM SY/T PRETORIA FOR TSO

REF: PRETORIA 2513 (NOTAL)

- 1. IN REFTEL, TSO PRETORIA INDICATED RECEIPT OF DAMAGED DISINTEGRATOR MOTOR STARTER SOLENOID FROM PORT LOUIS.
- 2. TSO REQUESTED REPLACEMENT SOLENOID FOR 380 VOLTS.
- 3. TO GET FURTHER INFORMATION ON PORT LOUIS DISINTEGRATOR, OC CONTACTED MANUFACTURER. AS A RESULT, THERE IS SOME CONFUSION AS TO WHAT IS NEEDED FOR YOUR DISINTEGRATOR.
- 4. MANUFACTURER INDICATED THAT UPON PORT LOUIS REQUEST, A 220 VAC, 50 CYCLE MOTOR WAS INSTALLED ON THE DISINTEGRATOR.
- 5. REFTEL FROM TSO INDICATES THAT STARTER SOLENOID DAMAGED BY 380 VAC, AND REQUESTS A 380 VOLT COIL. FROM THIS REQUEST, IT APPEARS THAT YOU PLAN TO RUN DISINTEGRATOR ON 380 VOLTS. THIS IS NOT POSSIBLE WITH PRESENT 220 VOLT UNCLASSIFIED

UNCLASSIFIED

PAGE 02 STATE 152254

DISINTEGRATOR MOTOR.

- 6. IT APPEAR THAT THE SOLENOID WAS CONNECTED ACROSS 2 PHASES OF A 380 VAC POWER LINE, RATHER THAN FROM PHASE TO NEUTRAL. IF THIS IS CORRECT, THEN YOU ONLY NEED A REPLACEMENT 220 VAC SOLENOID, AND PROPER POWER LINE CONNECTIONS.
- 7. IF IT IS NOT POSSIBLE TO GET 220 VAC FROM PROPER POWER LINE CONNECTIONS, THE 380 VAC SUPPLY WILL HAVE TO BE STEPPED DOWN THROUGH A TRANSFORMER, OR A COMPLETE NEW MOTOR-SOLENOID ASSEMBLY WILL BE REQUIRED. TRANSFORMER WOULD HAVE TO BE PROCURRED LOCALLY, OR IN EUROPE. A NEW MOTOR-SOLENOID SET FROM THE MANUFACTURER WILL COST APPROXIMATELY \$ 175.00.
- 8. ADVISE SY/T OF YOUR POWER SITUATION AND WHETHER YOU NEED ONLY SOLENOID (APPROX. DOLLARS 40) OR MOTOR-SOLENOID SET. IN EITHER CASE, ITEMS ARE POST FUNDED, SO PLEASE INCLUDE FISCAL DATA IN REPLY. SY/T WILL PHONE ORDER TO COMPANY TO GET PARTS AS QUICKLY AS POSSIBLE. ROGERS

UNCLASSIFIED

NNN

## Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

**Current Classification: UNCLASSIFIED** 

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 02 AUG 1973 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: n/a Disposition Approved on Date: Disposition Authority: n/a Disposition Case Number: n/a

Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:

Document Number: 1973STATE152254 Document Source: CORE

Document Unique ID: 00 Drafter: JFPERDEW Enclosure: n/a Executive Order: N/A Errors: N/A Film Number: n/a From: STATE

Handling Restrictions: n/a

Image Path:

Legacy Key: link1973/newtext/t19730861/aaaabszs.tel

Line Count: 82 Locator: TEXT ON-LINE

Office: ORIGIN SY

Original Classification: UNCLASSIFIED

Original Handling Restrictions: n/a Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 2

Previous Channel Indicators: Previous Classification: n/a Previous Handling Restrictions: n/a Reference: 73 PRETORIA 2513 (NOTAL) Review Action: RELEASED, APPROVED

Review Authority: boyleja Review Comment: n/a Review Content Flags: Review Date: 06 DEC 2001

**Review Event:** 

Review Exemptions: n/a
Review History: RELEASED <06-Dec-2001 by reddocgw>; APPROVED <01 MAR 2002 by boyleja>

**Review Markings:** 

Declassified/Released US Department of State EO Systematic Review 30 JUN 2005

**Review Media Identifier:** Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: DISINTEGRATOR PARTS PORT LOUIS FOR PSO FROM SY/T

TAGS: ASEC To: PORT LOUIS

Type: TE

Markings: Declassified/Released US Department of State EO Systematic Review 30 JUN 2005